

**REPORT SHEET  
FOR  
PERCOLATION AND SIX FOOT HOLE TESTING**

Subdivision Name Hamilton Estates County HAMP.  
 Total Number of Lots 49 Name of Applicant North American Land  
 Name of Certified Installer Responsible for Testing Mercede's Special Services  
 Installer Certification No. 54-94-0222 Installer Signature Wendell Mercede  
 Address P.O. Box 188 Capon Bridge

Type System	Lot Number	Percolation Test Results (Minutes per Inch of Fall)				Average Results	Six Foot Hole Results		Date Conducted
							Depth to Water	Depth to Rock	
<del>II</del>	1	240	60	90	144	22	6'		2/20/06
II	2	60	60	60	60	10			
I	3	144	180	120	180	26			
I	4	72	65	60	60	11			
<del>I</del>	<del>5</del>	<del>360</del>	<del>360</del>	<del>360</del>	<del>360</del>	<del>60</del> <sup>45</sup>			
II	6	130	180	240	180	30			
I	7	180	180	144	180	29			
II	8	360	240	360	240	50			
II	9	180	180	240	180	33			
I	10	360	360	360	240	55			
I	11	180	144	240	240	34			
I	12	360	180	240	480	53			
<del>II</del>	<del>13</del>	<del>360</del>	<del>480</del>	<del>480</del>	<del>360</del>	<del>90</del> <sup>60</sup>			
I	14	180	205	144	144	28			
I	15	180	240	180	180	33			
I	16	360	180	240	360	48			
I	17	240	180	240	180	35	6'		
<del>I</del>	<del>18</del>								
I	19	360	360	360	360	60	5'		
<del>I</del>	<del>20</del>								3/22/06

(Attach additional pages if needed)