SS-177, Revised 1-71

WEST VIRGINIA SEPTIC TANK INSPECTION FORM

)	Mampshul Health Department Installation Permit No. <u>ST-14-94</u> -38
	Name of Owner Wayne amoluny
	Address One Eagle Playa Suite-R
	Property Address Crossings Let # 135 Phase II
	DESCRIPTION & NUMBER OF UNITS SERVED
	Type Facility Served home No. Water Closets
	Lot Size sq. ft. Area suitable for sewage disposal installation sq.ft
	Source of Water Supply Well No. Lavatories
	No. Bedrooms No. Showers or Tubs No. Baths
	No. Garbage Grinders No. Automatic Washers
	SEPTIC TANK
	Material Conrete Length - x Width - x Depth - = _ cubic feet
	Liquid Depth ft. Liquid Capacity /000 gal.
1	Distance to: Dwelling 38.5 Water Supply //00' Nearest Property Line //00'
	SOIL ABSORPTION SYSTEM
	Type Drain Line Material Mucles Trench Width 34" Inches
	Trench Depth 18-28 Inches Total Absorption area in Trench Bottom 1200 sq. ft.
	Diameter of Drain Line 10" Inches Type Filter Media 11/14
*	No. of Drain Lines 4 Depth Filter Media Under Drain Line /// Inches
	Length of Each Line 100,100,100,100 ft. Depth Filter Media Over Drain Linein
	Distance of Disposal Field to: (a) Dwelling $13/1$
	(b) Water Supply 160 (c) Nearest Property Line 75
	An inspection of the septic tank system described herein disclosed that said system (MEETS DOES NOT MEET) the minimum standards established by the West Virginia State Department of Health.
	Date Sanitarian
	Date

SKETCH OF SYSTEM TO BE DRAWN ON BACK

Note: Copy of this inspection report must be given to owner and the original filed in the Health Department files. PERMANENT RECORD - DO NOT DESTROY.

