Lee Thompson -304-538-6355

REQUEST FOR SITE APPROVAL

	TO: Hardy Cour	icy Resith Depar	cment, roote	Lield, w.v.		
	FROM: Name ME	LBOURNE	Propers	i'es P	one 304.85	6-2957
	Address	P.O. BOX 5	67 Caf	on Brio	19 E. WV. 7	6711
(A)		ocation 31/2				
		hereby made for	r a site inv	estigation	to determine	the suitability
	() Septic System	n () Pit Privy	() Vault	Privy (Y	Other Site	ApprovaL
	The result requirements of I	s of a percola Design Standard				
	Depth of	test holes: Ø1	18", #2 18	", #3 18"	, #4 18 inche	3.
	Time for	water to fall 6	inches in te	st hole #1	360	_minutes
Lot#	41			#3 #4	60	- "
				TOTAL .	570	Minutes.
	A test ho provided to help	le bored or dug descrmine the				
	On the ba property lines a test holes, six		ations of bui	ldings, wa	ter supplies,	
	I (we), t correct and accu that this form <u>i</u> of this site by install a sewage	s not an applic the designated	t of my (our)	knowledge	. It is furth subsequent ac	er understood ceptance
	Owner's signatur				Date	
	Percolation test	conducted by:	Name Co	mbs	Excavai	ing
			Address RA	1 304	55 Bak	er N. Va. 2
	Date 2-2-6	2	Signature	Bandy	L. Combs	
	FOR HEALTH DEPT. USE ONLY					
	This is to the contents of Based on the inithis site (X) I system indicated	ormation provide	conducted a s led it is the suitable for	ite visit of opinion of the install	n subject pro the undersig	perty. ned that small sewage
	Title Sani	larian				
	water cut			, ,	/	hole
	Sete re-ebo	luated wi	the New 6	' Role	2-9-02	
					, F1	