ES-76 Revised 2/14 Page 2

REPORT SHEET FOR

PERCOLATION RATE TESTING AND SIX FOOT HOLE OBSERVATIONS

Subdivision Name County Humpshyre Total Number of Lots Name of Applicant Lawrence Kesse								
Total N	Number	of Lots			Nam	ne of Applicant	/ aurence Kes	38
Name	of Certif	ied Insta	ller Resp	onsible t	for Testing	*		
Installe	er Certifi	cation No	54	-A-U	08	Installer Signature	ful	/
Lot No.	Percolation Test Results (Minutes per 6" of Fall)				Avg Perc Rate (Min. per Inch)	Date Conducted	Sanitarian's 6 ft. Depth to Water	Hole Evaluation Depth to Rock
1	90	90	90	90	15 mon	2-10-25	NA	Nr
2	90	120	120	120	18.75 min	2-10-25	No	NA
3	120	90	90	no	17.5 min	2-10-25	NA	Au
	-			~	-	-		
		8						
		-						
			-			-		
			,					
				25				
						10.10-0.10 (0.10-0.10-0.10-0.10-0.10-0.10-0.10-0.10		

Attach additional sheets if necessary.